

Brass Crosses




Fig. 1




Fig. 2




Fig. 3

Ordering Information

Part Number	Figure	A (Female)	B (Female)	C (Female)	D (Female)	E (Ref.)	Working Pressure PSIG*
1225-1	1	½" NPT	½" NPT	½" NPT	½" NPT	2¼"	3750
HP1225-1						3"	4500
1045		¾" NPT	¾" NPT	¾" NPT	¾" NPT	3"	4500
1225-3	2	.843-.847	.843-.847	½" NPT	½" NPT	2¼"	3750
HP1225-3						3"	4500
2222-2		1.053-1.057	1.053-1.057	¾" NPT	¾" NPT	3"	4500
HP1225-4	3	.843-.847	.843-.847	.843-.847	.843-.847	3"	6000
2222-4		1.053-1.057	1.053-1.057	1.053-1.057	1.053-1.057	3"	4500