



**February 10, 2017**

**Product Information Bulletin – L7579 Date Code 8B16 to 1C17 Rework**

Please be advised we are reworking new/never installed L7579 filler valves with date codes of 8B16 to 1C17 covered by the February 3, 2017 field advisory. The rework manufacturing process will revert the product back to the previous revision prior to August second week 2016. This will make the valve no longer applicable to the field advisory. The reworked valves will have an “R” (for reworked) stamped near the date code.

All reworked valves will be fully factory tested according to RegO’s quality procedures.

Should you have any questions, please contact Bennett Allred at 336-446-7230.

**NOT Reworked L7579**



Date Code (01C17)

**Reworked L7579**



Date Code (01B17)

NOTE:  
The R stamp denoting rework can be located anywhere on the wrench flat where the date code is located.